

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans
 Run date
 21-Nov-14

 Time
 5:47 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 248 Const Calendar Day: 485 Date: 06-Jan-2011 Thursday Inspector Name: Wilcox, Jason Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 06:30 am 05:30 pm **Break:** 00:30 **Over Time:** 02:30

Federal ID: Location:

Reviewer: Jefferson, Paul Approved Date: 30-Jan-14 Status: Approved

Weather

Temperature 7 AM 40 - 50 12 PM 50 - 60 4PM 50 - 60

Precipitation Condition Partly Cloud

Working Day 🗸 If no, explain:

Diary: Dispute

General Comments

Partly cloudy and cool

See Thanh Le's diary for the W-Line and David Bradd's for the E-Line.

- •Met with Zack Lauria for possible bolt testing locations for today and to look at the misaligned holes for the Suspender Bracket at Panel Point 58 on the West Line. There are 2 holes drilled that intersect each other. One lines up with the hole in the Suspender Bracket, but the other one does not. Dan Hester said that there is an RFI for this, possibly from China. This will be addressed in the coming days.
- •0800 hrs Safety Meeting
- •Crossbeam 13 erected this morning to 10E. Step 3B minimum bolting has been met at Splice 9E/10E this morning and erection of the Crossbeam is acceptable.
- •Incident Report written by Rick Bettencourt for grinding/removal of blow through at the backing bar of the Top Deck weld. This is in reference to RFI-2290R00.
- •Review Plans and Specs
- Diaries

Accrued 2.5 hours of overtime documenting and covering the Contractor's hours.

